



Photo 1: Clearing and grubbing the Dinwoody Borrow Area (3/16/2015).



Photo 2: Clearing and grubbing the Dinwoody Borrow Area (3/31/2015).





Photo 3: Spreading chert cover material on the east side of Pole Canyon ODA (4/20/2015).



Photo 4: Construction of the South Sedimentation Basin at the Dinwoody Borrow Area (4/21/2015).





Photo 5: Spreading chert cover material on the east side of Pole Canyon ODA (4/29/2015).



Photo 6: Checking chert layer thickness by potholing (4/30/2015).





Photo 7: Rubber-tired compactor used to compact initial one-foot layer of Dinwoody cover material (5/6/2015).



Photo 8: Spreading of Dinwoody material over chert layer, Pole Canyon ODA east side (5/6/2015).





Photo 9: Removal of Dinwoody material from the Dinwoody Borrow Area (5/12/2015).



Photo 10: Spreading chert cover material on the west side of Pole Canyon ODA (5/21/2015).





Photo 11: Spreading chert cover material on the west side of Pole Canyon ODA (5/27/2015).



Photo 12: Construction of East Sedimentation Basin, near the east toe of Pole Canyon ODA (6/26/2015).





Photo 13: Spreading of Dinwoody material over chert layer, Pole Canyon ODA west side (7/17/2015).



Photo 14: Construction of South Central Sedimentation Basin (7/23/2015).





Photo 15: Spreading of Dinwoody material over chert layer, Pole Canyon ODA west side (7/23/2015).



Photo 16: Construction of run-on control ditch, Dinwoody Borrow Area (8/27/2015).





Photo 17: Installation of intake structure for A-Panel runoff ditch into 42-inch CMP under mine haul road (9/16/2015).



Photo 18: South Central Sedimentation showing TRM on side slopes and interior rock berm (9/16/2016).





Photo 19: Construction of West-Side Ditch (9/16/2015).



Photo 20: Hydromulch application on Dinwoody cover, east side of Pole Canyon ODA (10/6/2015).





Photo 21: Hydromulch application on Dinwoody cover, west side of Pole Canyon ODA. Note relocated Blast Compound at left center (10/7/2015).



Photo 22: Grouting riprap in the South Central Chute, upstream of Saddle Basin (10/22/2015).





Photo 23: Grouting riprap in the West Side Runoff Ditch (10/22/2015).



Photo 24: West slope of Pole Canyon ODA with completed cover and hydromulch (10/22/2015).





Photo 25: West slope of Pole Canyon ODA with hydromulch and straw wattles (11/4/2015).